


LEAD SLATES

- For use on any pitched or flat roofs.
- Suits all common pipe diameters and pitch.
- Easily dressed to shape.
- Suitable for flue pipes.
- Recommended by 

Lead slates provide weather-tight joints where flue pipes and soil stacks penetrate a slate, tile, asphalt, felt or lead covered roof.

The flexibility of lead allows the slate base to be dressed to tiles of all profiles, avoiding wind lift or chatter problems. Premium Lead Slates are cut for BS EN 12588.

Code 4 rolled lead sheet and fabricated by lead welding. Slate upstands are available in five diameters from the 50mm to 150mm, at angles of 30° and 45° to the base for pitched roofs and 90° for flat roofs.

The base dimensions of the slates are 450mm x 450mm and the minimum upstand height at the saddle side of the pipe-base joint is 150mm. Non standard sizes are available. When stipulating dimensions, remember to specify the pipe dimension and the slate pitch required.

- Select a lead slate with an upstand angle suitable to the pitch of the roof of internal diameter such that it allows about 2mm tolerance over the external diameter of the pipe.
-
- Always apply coat of Pre-pat or Patination Oil to all exposed surfaces, as well as the underside of the landing edge.
- Fit over the pipe and on a pitched roof finish the top edge of tile with a welt.
- When fitting over cast iron pipes, allow extra height to the lead upstand so that it may be dressed into the top of the pipe.
- When fitting over the plastic pipes you can obtain a solvent welded collar that will provide a weathering over the top of the pipe.

LOT SIZES

50mm dia. (2") x 150mm
75mm dia. (3") x 150mm
100mm dia. (4") x 150mm
125mm dia. (5") x 150mm
150mm dia. (6") x 150mm

upstand 5 slates per box
upstand 5 slates per box
upstand 5 slates per box
upstand 5 slates per box
upstand 5 slates per box

HEALTH & SAFETY ADVICE

- Keep out of reach of children.
- When working with lead, follow standard health and safety procedures as laid out in Control of Lead at Work Regulations 2002. Always wash hands well before eating, drinking or smoking.
- Remove lead residues from skin after working with lead metal by washing with soap and bodywash.
- Lead is a dense material. Take suitable precautions when lifting or carrying.

PRODUCT DESCRIPTION AND PROPERTIES

Composition:

Density of lead:

Melting point of lead:

Base dimensions:

Upstand height:

Upstand angle to base:

Weight:

Lead alloy sheet manufactured to BS EN 12588 Code 4.
11,340 kg.m⁻³
327°C
450mm x 450mm
≥150mm
30°, 45° or 90°
5.5kg (approx.) Per slate